

Type Approval Certificate

This is to certify that the undernoted product(s) has/have been tested with satisfactory results in accordance with the relevant requirements of the Lloyd's Register Type Approval System.

Manufacturer	Intelligent Platforms LLC
Address	2500 Austin Drive, Charlottesville, VA, 22911-8319, United States of America
Place of Production	APLEX TECHNOLOGY INC. 2F, No.249, Jian Yi Road, Zhonghe Dist., New Taipei City, 235, Taiwan
Type	PC Monitors
Description	RXi – Panel PC, RXi – Web Panel, RXi – Industrial Monitor, QuickPanel-XP and QuickPanel+
Trade Name	EMERSON
Application	Marine application for use in environmental category ENV1, ENV2, for equipment on the bridge and deck zone, as defined in LR Type Approval Test Specification No. 1, March 2019
Specified Standard	Manufacture's product specification
Ratings	Ingress Protection: IP 66 Power supply: 24V DC RXi - Panel PC : IC758CXXXXXXXXXX IC758CSWA07PC, IC758CSWA07PC64, IC758CSWA07PC128, IC758CSWB07PC, IC758CSWB07PC64, IC758CSWB07PC128, IC758CSSA10PC, IC758CSSA10PC64, IC758CSSA10PC128, IC758CSWA10PC,

19th Floor, 550 Yan An dong Road, Shanghai,
Huangpu District, China

Ke Lin Zhang

Senior Specialist to Lloyd's Register
Classification Society (China) Co Ltd
A member of the Lloyd's Register group

Lloyd's Register Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'Lloyd's Register'. Lloyd's Register assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant Lloyd's Register entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.

Type Approval Certificate

IC758CSWA10PC64,IC758CSWA10PC128, IC758CSSB10PC, IC758CSSB10PC64,
IC758CSSB10PC128, IC758CSWB10PC,IC758CSWB10PC64, IC758CSWB10PC128,
IC758CSSA12PC, IC758CSSA12PC64, IC758CSSA12PC128,IC758CSWA12PC,
IC758CSWA12PC64, IC758CSWA12PC128,
IC758CSWB12PC128,IC758CSSA15PC, IC758CSSA15PC64, IC758CSSA15PC128,
IC758CSWA15PC, IC758CSWA15PC64,IC758CSWA15PC128, IC758CSSB15PC,
IC758CSSB15PC64, IC758CSSB15PC128, IC758CSWB15PC,IC758CSWB15PC64,
IC758CSWB15PC128, IC758CSWA19PC, IC758CSWA19PC64,
IC758CSWA19PC128,IC758CSWB19PC, IC758CSWB19PC64,
IC758CSWB19PC128, IC758CSWA24PC,
IC758CSWA24PC64,IC758CSWA24PC128, IC758CSWB24PC, IC758CSWB24PC64,
IC758CSWB24PC128, IC758COWA07PC,IC758COWA07PC64,
IC758COWA07PC128, IC758COWB07PC128,
IC758COWA10PC,IC758COWA10PC64, IC758COWA10PC128,
IC758COWB10PC128, IC758COWA12PC64,IC758COWA12PC128,
IC758COWB12PC128, IC758COWA15PC64,
IC758COWA15PC128,IC758COWB15PC128, IC758CSSB12PCX128,
IC758CSSB12PCX256, IC758CSSB12PCX512,IC758CSSC12PCX128,
IC758CSSC12PCX256, IC758CSSC12PCX512,
IC758CSWB12PCX128,IC758CSWB12PCX256, IC758CSWB12PCX512,
IC758CSWC12PCX128, IC758CSWC12PCX256,IC758CSWC12PCX512,
IC758CSSB15PCX128, IC758CSSB15PCX256,
IC758CSSB15PCX512,IC758CSSC15PCX128, IC758CSSC15PCX256,
IC758CSSC15PCX512, IC758CSWB15PCX128,IC758CSWB15PCX256,
IC758CSWB15PCX512, IC758CSWC15PCX128,
IC758CSWC15PCX256,IC758CSWC15PCX512, IC758CSWB19PCX128,
IC758CSWB19PCX256, IC758CSWB19PCX512,IC758CSWC19PCX128,
IC758CSWC19PCX256,IC758CSWC19PCX512, IC758CSWB24PCX128,
IC758CSWB24PCX256, IC758CSWB24PCX512,IC758CSWC24PCX128,
IC758CSWC24PCX256, IC758CSWC24PCX512,
IC758COWB12PCX128,IC758COWB12PCX256, IC758COWB12PCX512,
IC758COWC12PCX128,
IC758COWC12PCX256,IC758COWC12PCX512, IC758COWB15PCX128,
IC758COWB15PCX256, IC758COWB15PCX512,IC758COWC15PCX128,
IC758COWC15PCX256, IC758COWC15PCX512

19th Floor, 550 Yan An dong Road, Shanghai,
Huangpu District, China

Lloyd's Register Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'Lloyd's Register'. Lloyd's Register assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant Lloyd's Register entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.

Type Approval Certificate

RXi – Web Panel : IC757CXXXXXXX
IC757CSW07WHMI, IC757CSS10WHMI, IC757CSW10WHMI, IC757CSS12WHMI,
IC757CSW12WHMI, IC757CSS15WHMI, IC757CSW15WHMI, IC757CSW19WHMI,
IC757CSW24WHMI, IC757COW07WHMI,
IC757COW10WHMI, IC757COW12WHMI, IC757COW15WHMI

RXi – Industrial Monitor : IC756CXXXXXX
IC756CSW07IM, IC756CSS10IM, IC756CSW10IM, IC756CSS12IM, IC756CSW12IM,
IC756CSS15IM, IC756CSW15IM, IC756CSW19IM, IC756CSW24IM,
IC756COW07IM, IC756COW10IM, IC756COW12IM, IC756COW15IM

QuickPanel – XP View : IC760CXXXXXXX
IC760CSW07CDA, IC760CSS10CDA, IC760CSW10CDA, IC760CSS12CDA,
IC760CSW12CDA, IC760CSS15CDA, IC760CSW15CDA, IC760CSW19CDA,
IC760CSW24CDA
IC760COW07CDA, IC760COW10CDA, IC760COW12CDA, IC760COW15CDA

QuickPanel – XP View & Control : IC761CXXXXXXXXXX
IC761CSW07CDA, IC761CSS10CDA, IC761CSW10CDA, IC761CSS12CDA,
IC761CSW12CDA, IC761CSS15CDA, IC761CSW15CDA, IC761CSW19CDA,
IC761CSW24CDA, IC761COW07CDA, IC761COW10CDA, IC761COW12CDA,
IC761COW15CDA

QuickPanel+ : IC755CXXXXXXX
IC755CSW07CDA, IC755CSS10CDA, IC755CSW10CDA, IC755CSS12CDA,
IC755CSW12CDA, IC755CSS15CDA, IC755CSW15CDA, IC755CSW19CDA,
IC755CSW24CDA
IC755COW07CDA, IC755COS10CDA, IC755COW10CDA, IC755COS12CDA,
IC755COW12CDA, IC755COS15CDA, IC755COW15CDA

RXi2 – LP IPC : R2LXXXXXXX
R2L0N1A1A, R2L0N1A0A, R2L0N2A1A, R2L0N1B1A, R2L0N1B0A, R2L0N2B1A,
R2L0N1A1B, R2L0N1A0B, R2L0N2A1B, R2L0N1B1B, R2L0N1B0B, R2L0N2B1B,
R2L0N1A1C, R2L0N1A0C, R2L0N2A1C, R2L0N2A0C, R2L0N1B1C, R2L0N1B0C,
R2L0N2B1C, R2L0N2B0C

This certificate is not valid for equipment, the design, ratings or operating parameters of which have been varied from the specimen tested. The manufacturer should notify Lloyd's Register Classification Society (China) Co Ltd of any modification or changes to the equipment in order to obtain a valid Certificate.

The Design Appraisal Document No. LR2002569TA and its supplementary Type Approval Terms and Conditions form part of this Certificate.

19th Floor, 550 Yan An dong Road, Shanghai,
Huangpu District, China

Lloyd's Register Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'Lloyd's Register'. Lloyd's Register assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant Lloyd's Register entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.